

FIG. 1




FIG. 2a




FIG. 2b








FIG. 2C

3/16

555



9/1/4



5/16

555




FIG. 3b(1)




FIG. 3b(2)










FIG. 3b(3)

9/1/9



9/1



9/8

FIG. 3E(3)




FIG. 3E(1)




FIG. 3E(2)





FIG. 3E(3)

9/6



9/1/01

1000





FIG. 5

9/1/11

1000






FIG. 6

12/16

1000



\vec{x} \vec{y} \vec{z}



\vec{x} \vec{y} \vec{z}

FIG. 7




FIG. 8a




FIG. 8b




FIG. 9a




FIG. 9b




FIG. 10a




FIG. 10b




FIG. 11a




FIG. 11b